9900333496

Fie Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN

Date of Inspection	Remarks
26/10/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0181, W0189, W0196, W0179,

9900333496

Fie Inspection Details

Number of Trees	Any Other Information	Name
0		G NAGABHUSHAN

Date of Inspection	Remarks
26/10/2016	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Segment End		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	SIDHEGOWDA	26/10/2016	25/11/2016	COMPLETED
EE	DODDAIAH	26/10/2016	25/11/2016	COMPLETED
AEE	JAYALINGAPPA	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED
AE	G NAGABHUSHAN	26/10/2016	25/11/2016	COMPLETED

Zone: DASARAHALLI **Ward No:** 13 **Ward Name:** Mallasandra **Street ID:** W0181, W0189, W0196, W0179,